

DEM

25X1A

[REDACTED]

25X1A

TOP SECRET 261800Z CITE [REDACTED] 0076

IMMEDIATE [REDACTED] INFO IMMEDIATE [REDACTED]

OXCAR

[REDACTED]

A. BX6747

B. FLASH REPORT AFTER PROCESSING

C. TYPE 1

D. C

E. THE FILM ARRIVED IN GOOD PHYSICAL CONDITION. MISSION HAD GOOD RESOLUTION, NORMAL EXPOSURE, METERING AND OPERATIONAL DATA RECORDING. FILM WAS SLIGHTLY HIGH IN APPARENT CONTRAST. MINUS DENSITY LINES WERE NOTED IN ALL FWD FRAMES 5/8 INCHES FROM LEADING EDGE AND 1 1/4 INCHES FROM TRAILING EDGE. A MINUS DENSITY LINE WAS OBSERVED IN ALL AFT FRAMES 2 1/4 INCHES FROM THE LEADING EDGE. AN EXTREMELY FINE PLUS DENSITY SCRATCH OCCURRED 5/8 INCHES FROM LEADING EDGE, INTERMITTENTLY THROUGHOUT THE MISSION. DATA CHAMBERS WERE COCKED APPROXIMATELY 5 DEGREES TO LEFT OF PERPENDICULAR IN ALL FRAMES, CAUSING SOME DATA CHAMBERS TO ENTER IMAGERY. EXCESSIVE BLURRING CAUSED BY CAGING WAS NOTED FROM FRAMES 1247 TO 1265.

TOP SECRET

BT

00 10 36Z

25X1A

25X1A

25X1A

R

R

W

✓

25X1A

ZCZC767

FTP934/0270001 ZPO [REDACTED] ZFF4

BT

XXXXX

[REDACTED] 25X1A

25X1A

TOP SECRET 262352Z JAN 68 CITE [REDACTED] 2835

IMMEDIATE [REDACTED] INFO [REDACTED]

25X1A

25X1A

A. BX 6847

25X1A

B. INS TAPE EVALUATION REPORT

C. INS 310

D. 26/0915Z

E. 1. SATISFACTORY

2. SATISFACTORY

3. SATISFACTORY

4. SATISFACTORY

5. SATISFACTORY

6. SATISFACTORY

7. SATISFACTORY

8. SATISFACTORY

9. SATISFACTORY

10. SATISFACTORY

F. A LINE OF DATA WAS GARBLED BETWEEN ELAPSED TIME 6763 AND 6773. A LINE OF DATA WAS ADDED BETWEEN ELAPSED TIME 7546 AND 7555, AND BETWEEN ELAPSED TIME 12635 AND 12842. TAPE APPEARS SATISFACTORY. TAPE EVALUATION PERTAINS TO CAMERA OPERATION ONLY.

TOP SECRET

27 JUN 68 06 30Z

HDFXRXEAX MR

UDYGVONL3111" : 782E1A062ALA876 YKA313

OO RUEIWM RUEIWF

DE RUALYK 154 0270515

ZNY XXXXX

O 270500Z ZFFI

BT

XXXXX

TO BE PROCESSED BY SPECIAL DESIGNEES ONLY

25X1A

25X1A

TOP SECRET *270500Z Jnn* ~~270500Z~~ 68 CITE 0079

IMMEDIATE

INFO JYED

25X1A

25X1A

25X1A

A. SX6847

B. FILM EVALUATION REPORT

C. TYPE IC

D. FULTRON *201/* ~~0000~~ MX578/47 SEC/86 DEGREES F

E. 2.61/2.67 T.26 T.27

F. 3401/404-2-10-7

G. (1) GOOD

(2) GOOD

(5) OPERATIONAL

Approved For Release 2002/06/13 : CIA-RDP69B00041R001600010047-0

(6) NORMAL

(7) 10 PERCENT OVER LAND 40 PERCENT OVER WATER

H. O.N. DISPOSITION TO E.K. THREE DUPE POS TO NATIONAL CUSTOMERS.
SEVEN DUPE POS AND 1 DUPE NEG TO THEATRE CUSTOMERS. NORMAL STARTUP
AND SHUT DOWN. MINUS DENSITY LINES WERE NOTED IN ALL FWD FRAMES
3" FROM LEADING EDGE AND 1 1/4" FROM TRAILING EDGE. A MINUS
DENSITY LINE WAS OBSERVED IN ALL AFT FRAMES 2 1/4" FROM THE LEADING

25X1A

PAGE 2 0079 T O P S E C R E T

EDGE AND EXTREMELY FINE PLUS DENSITY SCRATCH OCCURED 5/8" FROM
LEADING EDGE INTERMITTENTLY THROUGHOUT THE MISSION. DATA CHAMBERS
WERE COCKED APPROXIMATELY 5 DEGREES TO LEFT OF PERPENDICULAR IN
ALL FRAMES, CAUSING SOME DATA CHAMBERS TO ENTER IMAGE AREA.
EXCESSIVE BLURRING CAUSED BY GAGEING APPARENT IN FRAMES 1247
TO 1265. FRAMES 1 THRU 4 TITLING IN IMAGE AREA. FRAMES
327 AND 328 HANDLING MARKS. FRAME 485 PINHOLES. MINUS DENSITY
LINE 3/4" FROM TRAILING EDGE. OVERLAP IN FRAMES 1001 THRU 1036.
DATA RECORDING CHAMBER DOUBLE EXPOSED ON 1023 AND 1024. 1355
THRU 1364 SHUTDOWN FACTORY SPLICE FRAME 1240. FRAME 1241 TRACKED
OFF ON TRAILING EDGE.

T O P S E C R E T

BT

DCM

NNNNZCZC869A542

374/290303Z ZFF-1 ZPO

25X1A

BT

XXXXX

25X1A

TOP SECRET 290258Z JAN 68 CITE

7505

25X1A

IMMEDIATE

25X1A

25X1A

REF A. BX6848

25X1A

B. 2441

MSN BX6847 WAS AN EXCELLENT MISSION EXCEPT FOR A VERY FEW FRAMES THAT HAD APPROX 5 INCH OVERLAP. THIS COULD POSSIBLY BE CAUSED BY AIRCRAFT TURNS, TURN ON/OFF OR POSSIBLY AN OCCASIONAL METERING PROBLEM. UNTIL IT IS DETERMINED EXACTLY WHY THIS OVERLAP OCCURRED REQUEST THE OTHER TWO TYPE I CAMERAS BE USED OR, IF NECESSARY, IC BE USED IN BACK-UP ACFT.

TOP SECRET

BT

Due to Unstart ??

DCM

069
ZZCZC063JEDT T

FTP130/011928Z ZPO

BT

XXXXX

25X1A

28239

25X1A

T O P S E C R E T 011920Z FEB 68 CITE

2882.

PRIORITY

INFO

25X1A

25X1A

25X1A

25X1A

A. BX 6847

B. INS FILM CORRELATION REPORT

C. INS 010

D. 1. SATISFACTORY

2. SATISFACTORY

3. SATISFACTORY

4. SATISFACTORY

5. SATISFACTORY

6. SATISFACTORY

7. SATISFACTORY

8. SATISFACTORY

9. SATISFACTORY

10. FILM CLOCK SHOWS A BIAS OF MINUS 47 TO 49 SECONDS

THROUGHOUT THE MISSION.

E. SATISFACTORY CORRELATION HAS BEEN ACHIEVED ON THIS MISSION.

T O P S E C R E T

BT

25X1D

Next 8 Page(s) In Document Exempt